

Form IV
(See Rule 13)
ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier health care facility(HCF), or common bio-medical waste treatment facility (CBWTF)]

Return No : 6529912

Period : 2024

1. Particulars of the Occupier	
(i) Name of the authorized person (Occupier or operator of facility):	<i>SNG Envirosolutions Pvt Ltd</i>
(ii) Name of HCF or CBMWTF:	<i>SNG ENVIROSOLUTIONS PRIVATE LIMITED</i>
(iii) Address for Correspondence:	<i>Mouza – Saharjora, J.L No. 26, P.O. & P.S. – Borjora</i>
(iv) Address of Facility:	<i>Mouza – Saharjora, J.L No. 26, P.O. & P.S. – Barjora</i>
(v) Tel. No.:	<i>9330395322</i>
(vi) Fax. No.:	<i>-</i>
(vii) E-mail ID:	<i>sngenviro@gmail.com</i>
(viii) URL of Website:	<i>www.sngenviro.com</i>
(ix) GPS coordinates of HCF of CBMWTF:	<i>23.39328(Lat.) 87.25471(Long.)</i>
(x) Ownership of HCF or CBMWTF:	<i>Private</i>
(xi) Status of Authorization under the BMW (Management and Handing) Rules:	<i>Authorization No.: D0013749 Valid Upto: 30/06/2028</i>
(xii) Status of Consents under Water Act and Air Act.:	<i>Valid Upto: 30/06/2028</i>
2. Type of Health Care Facility	
HCF/CBMWTF Type:	<i>CBMWTF</i>
(i) Number healthcare facilities covered by CBMWTF:	<i>797</i>
(ii) No. of beds covered by CBMWTF:	<i>20106</i>
(iii) Installed treatment and disposal capacity of CBMWTF:	<i>6500</i>
(iv) Quantity of BMW treated or disposal by CBMWTF:	<i>1422815</i>
3. Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	<i>Yellow Category: 1120023 Red Category: 190138 White Category: 23173 Blue Category: 89481 General Solid Waste: 508</i>
4. Details of the Storage, Treatment, Transportation, Processing and Disposal Facility Details	
(i) Details of the on-site storage facility:	<i>Size: 12019 Capacity: 25000 Provision of on-site storage: Covered shed having storage area 75.72 sq. m</i>

(ii) Disposal Facility:	Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)
	<i>Incinerators</i>	<i>1</i>	<i>5000 kg</i>	<i>1120023</i>
	<i>Shredder</i>	<i>1</i>	<i>250 kg / Hour</i>	<i>159935</i>
	<i>Autoclaves</i>	<i>1</i>	<i>1000 Ltr. / Batch</i>	<i>190137</i>
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	<i>286124.0</i>			
(iv) No of vehicles used for collection and transportation of BMW:	<i>24</i>			
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum	Type of waste	Quantity Generated	Where disposal	
	<i>Ash</i>	<i>95734</i>	<i>WBWML, Saltora</i>	
	<i>ETP Sludge</i>	<i>227</i>	<i>Incinerated Inhouse & disposed with ash at WBWML, Saltora</i>	
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	<i>Inhouse</i>			
5. Do you have BMW management committee:	<i>yes</i>			
details:	<i>BMW Committee MoM</i>			
6. Training Conducted on BMW Details				
(i) Number of training conducted on BMW Management:	<i>196</i>			
(ii) Number of personnel trained:	<i>1400</i>			
(iii) Number of personnel trained at the time of induction:	<i>536</i>			
(iv) Number of personnel not undergone any training so far:	<i>0</i>			
(v) Whether standard manual for training is available:	<i>yes</i>			
(vi) Any other information:	<i>All vehicles are GPS enabled</i>			
7. Details of the accident occurred				
(i) No. of accident occurred:	<i>0</i>			
(ii) Number of the persons affected:	<i>0</i>			
(iii) Remedial Action taken:	<i>NA</i>			
(iv) Any Fatality occurred, details:	<i>0</i>			
8. Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	<i>Yes</i>			
Details of Continuous online emission monitoring systems installed:	<i>Model: CEMS-SPN-N03, Product ID:ENE03264</i>			
9. Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	<i>Yes</i>			
10. Is the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	<i>Yes</i>			

11. Any other relevant information:

Cyclone Separator, Bag Filter & Filtration unit with Ceramic Candles are installed as APCD.

Name and Signature of the Head of the Institution

Date :25/04/2025

Place : Bankura